

SECTION 13.0

Photograph Log

**PHOTOGRAPH LOG
GRANITE STATE LANDFILL
DALTON, NH**



Photo 1: Northerly view of overall GSL site (10/19/23).



Photo 2: Headwater wetland to intermittent stream (9/5/23). The monitoring well is located outside of the wetland.



Photo 3: Dry intermittent stream (7/21/23).



Photo 4: Intermittent stream impact area (9/5/23).



Photo 5: Forested/Shrub Emergent wetland (8/31/23).



Photo 6: Joe our weed within scrub-shrub area (8/31/23).



Photo 7: Dense wetland vegetation (7/7/23).



Photo 8: Spruce-Fir forested wetland (8/31/23).



Photo 9: Needle-leaved wetland in project area (8/31/23).



Photo 10: Bog wetland abutting original project area (8/31/23).



Photo 11: Former Beaver Pond within main wetland complex (8/31/23).



Photo 12: Alder Brook west of site (8/31/23).



Photo 13: Vernal Pool (VP-3) 4/28/23.



Photo 14: Vernal Pool (VP-4) 4/28/23.



Photo 15: Vernal Pool (VP-5) 4/28/23.



Photo 16: Vernal Pool (VP-6) 7/7/23.



Photo 17: Vernal Pool (VP-7) 7/7/23.

P:\1000s\1003.24\Source Files\Wetlands App\General Photo Log\Photo Log.docx