N.H. PETROLEUM REIMBURSEMENT FUND PROGRAM UNIT-BASED COSTS:

POINT-OF-ENTRY SYSTEMS & BOTTLED WATER



Oil Fund Disbursement Board

Point-of-Entry (POE) Treatment - Effective Jan. 1, 2023	Unit	Not-to-Exceed ("NTE") Rate	POE Treatment - (continued)	Unit	Not-to-Exceed ("NTE") Rate
Site evaluation	Each	\$470.25	Water sampling without POE system maintenance,	Each	\$278.75
Site installations		\$428.75	including 1-3 samples		
Furnish and install backwashing filter		\$2,222.50	Water sampling during POE system maintenance,		\$172.50
Service/maintain backwashing filter		\$154.75	including 1-3 samples		
Furnish and install water softener (0 to 3 mg/L iron)		\$2,401.25	Remove, clean, sanitize POE component; replumb		\$365.00
Furnish and install water softener (3 to 10 mg/L iron)		\$2,853.00	water supply to original configuration, as appropriate		
Service/maintain water softener and brine tank		\$187.25	Transport and dispose POE components		\$102.50
Furnish and install residential aerator		\$6,603.75	Technician labor - blended rate (including clerical,	Hour	\$118.75
Service/maintain residential aerator		\$211.00	treatment, project manager, principal)		
Furnish and install air injection unit		\$2,625.00	Addtional materials and supplies	Various	Market Retail Cost
Service/maintain air injection unit		\$222.25			
Furnish and install granular activated carbon contactor - 2 CF		\$1,771.25	Bottled-water - Effective January 2023	Unit	Not-to-Exceed
Furnish and install granular activated carbon contactor - 3 CF		\$2,410.00			("NTE") Rate
Furnish and install granular activated carbon contactor - 4 CF		\$3,107.50	Bottled Spring Water	Gallon	Cost + 10%
Service/maintain carbon contactor, no re-bed		\$113.50			
Furnish and install UV sterilizer		\$1,915.00			
Service and replace UV lamp in UV sterilizer		\$360.00			
Furnish and install water meter		\$437.50			
POE maintenance coordination and site visits		\$136.00			
Service and replace air stripper pump		\$1,638.33			
Service and re-bed, and dispose used carbon	Cubic Foot	\$663.75			
Service, remove and dispose of used carbon, no re-bed		\$273.75			
Service and bed carbon contactors		\$331.00			
Furnish and install 2 X 10, 5 micron cartridge filter assembly	Each	\$230.75			
Provide 2 X 10, 5.0 micron cartridge filter		\$9.50			
Furnish and install 4 X 10, 5 micron cartridge filter assembly		\$411.25			
Provide 4 X 10, 5.0 micron cartridge filter		\$29.25			
Furnish and install 4 X 20, 5 micron cartridge filter assembly		\$717.00			
Provide 4 X 20, 5.0 micron cartridge filter		\$58.25			
Service any size cartridge filter		\$121.00			
Service/maintain calcite neutralizer		\$206.00			