

**Table 4  
SUMMARY OF SITES CLOSED  
BETWEEN  
OCTOBER 1, 2010 AND SEPTEMBER 30, 2011**

SITE NAME	SITE NUMBER	SITE ADDRESS	COMMENTS	REMEDIAL ACTIONS PERFORMED	INSTITUTIONAL CONTROLS	ACREAGE
Freudenberg-NOK IPC Lower Dam #031.07	200607122	Route 3A, Bristol	Contaminated sediments accumulated behind dam.	Sediments removed in advance of dam removal.	None	0.1
Freudenberg-NOK - IPC Upper Dam #-31.03	200607121	Route 3A, Bristol	Contaminated sediments accumulated behind dam.	Sediments removed in advance of dam removal.	None	0.1
102 Granite Street	200701007	102 Granite Street, Berlin	Former dry cleaner. Containerized wastes, asbestos-containin materials, lead-based paint, and underground storage tank.	Containerized wastes disposed of properly. Abatement of asbestos and lead-based paint. Building demolition. Tank removed and properly disposed of.	None	0.3
Cheshire County Court House	198603043	12 Court Street, Keene	Contaminants not detected in Phase II Environmental Site Assessment.	None	None	1.5
3-5 Curtis Drive	201011000	3-5 Curtis Drive, Nashua	No contaminants detected during Phase II Environmental Site Assessment	None	None	0.5
Gardner Mountain	201102002	Lyman	Former copper and lead mine. Lead detected in soils above standards.	Soil exceeding the site specific soil remediation standard (based on risk assessment) removed and properly disposed of at permitted facility.	Activity and Use Restriction	1,081
95 Portsmouth Avenue Property	200908044	95 Portsmouth Avenue, Exeter	Groundwater contamination interpreted to be from an upgradient property. NHDES is investigating the upgradient source.	None	Will eventually be included within the groundwater management zone under a groundwater management permit that will be issued to the upgradient source owner.	0.78
Bartlett School	199512012	56 Mt. Forist Street, Berlin	No contaminants detected or reported.	None	None	1.4
Former Consolidated Freightways	199712006	835 Gold Street, Manchester	Petroleum contaminated soil and groundwater.	Petroleum contaminated soils removed and disposed at permitted facility.	Groundwater management permit for long-term monitoring of natural attenuation of groundwater contaminants. Site is being managed by the Oil Remediation & Compliance Bureau.	3.42
Ledge Road Area	200711031	Ledge Road, Windham	Explosives related groundwater contamination - nitrate	Blasting operations ceased and groundwater quality was monitored until contaminant concentrations consistently met Ambient Groundwater Quality Standards.	None	46.6
Granite State Plating	199306022	28 Patriots Way, Rochester	Reported release of cyanide and filtered metals to ground surface. No violations of soil or groundwater standards detected.	None	None	1
Post Road Plaza Site	199409066	Route 101A, Merrimack	Chlorinated volatile organic compounds detected in groundwater above standards.	Monitored natural attenuation until groundwater contaminant concentrations consistently met groundwater standards.	None	18.4
Hitchiner Manufacturing Landfill	198508002	Milford	Past exceedance of background metals concentrations with no groundwater standards violations.	Landfill was capped. Removal of contaminated soils.	Release Detection Permit in place which requires long-term groundwater quality monitoring. Site is being managed under the Landfill/Lined Lagoon Project	1
Northern Elastomeric, Inc.	199008042	Brentwood	Low concentrations of PCBs in shallow soils.	PCB-contaminated soils were capped with bituminous pavement.	Activity and Use Restriction Groundwater Management Permit - released	39.5
52 Clark Road Site	199911049	52 Clark Road, Londonderry	Initially reported dissolved metals in monitoring wells exceeded groundwater standards. Subsequent monitoring results indicate the initial results were erroneous and not representative of actual conditions.	None	None	8.5
Former Raytheon Facility	199607046	7 Redmond Road, Nashua	Chlorinated volatile organic compounds previously detected in site groundwater above groundwater standards. Determined to be due to on-site migration from another property. - Site groundwater now meets groundwater standards.	Monitored natural attenuation.	None	8.15

**Table 4  
SUMMARY OF SITES CLOSED  
BETWEEN  
OCTOBER 1, 2010 AND SEPTEMBER 30, 2011**

SITE NAME	SITE NUMBER	SITE ADDRESS	COMMENTS	REMEDIAL ACTIONS PERFORMED	INSTITUTIONAL CONTROLS	ACREAGE
Former Brockhouse Corp.	198901005	25 Lowell Street, Rochester	Chlorinated volatile organic compounds detected in groundwater above groundwater standards.  Discarded drums formerly present in tree-line adjacent to river.	Monitored natural attenuation until groundwater contaminant concentrations met groundwater standards. All drums removed.	None	5.2
Camp Wicosuta	200006011	West Shore Road, Hebron	Silver in soils above soil standards - beneath a building.	The silver-contaminated soils are being managed under a Notice of Activity and Use Restriction.	Activity and Use Restriction	83
Yankee Barn Homes, Inc.	198604182	131 Yankee Barn Road, Grantham	Reported groundwater standard violation for acetone. Lead contaminated soils in wood burning area.	Monitored natural attenuation until groundwater consistently met groundwater standards. Soil was removed for off-site disposal at permitted facility.	None	22
Organometallics, Inc.	198401064	Rte. 111 & Starwood Dr., Hampstead	Mercury detected above soil standards in soils within and below a septic system. No groundwater impacts.	Contaminated soil was removed and disposed of at a properly permitted facility.	None	5.02
Midas Muffler Shop	200505074	840 Second Street, Manchester	Tetrachloroethene reportedly detected slightly above groundwater standard.	Monitored natural attenuation until groundwater consistently met groundwater standards.	None	1
Northeast Glass & Aluminum, Inc.	198604248	28 Cottage Street, Littleton	Tetrachloroethene reportedly detected slightly above groundwater standard. Groundwater standard violation was not confirmed during additional monitoring rounds.	None	None	1
16 Squamscott Road	199812085	16 Squamscott Road, Newfields	Tetrachloroethene and trichloroethene detected in soil above soil standards.	Contaminated soil was removed and disposed of at a properly permitted facility. No groundwater impacts.	None	5.5
Green Valley 55267 Former Getty	199511007	233 South Broadway, Salem	Chlorinated volatile organic compounds reported in groundwater above groundwater standards.	Monitored natural attenuation until groundwater consistently met groundwater standards.	None	1
Former Goodreault's RV Sales	199108007	96 Plaistow Road, Plaistow	Arsenic detected in groundwater sample at concentration above groundwater standard.  Initial groundwater results were determined to be erroneous and not representative of actual conditions.	None	None	10
Sanel Block	200912001	45A - 49 South Main Street, Concord	Polynuclear aromatic hydrocarbons detected in soils and ash at concentrations above the soil standards. No groundwater impacts.	Contaminated soil and ash material were removed and disposed of at a permitted facility.	None	0.79
The Elliot at Rivers Edge (Fmr. Jac Pac)	199904017	163 Hancock Street Manchester, NH	Petroleum contaminants in soil and groundwater. Redeveloped by Elliot Hospital	Petroleum tanks removed. Contaminated soils removed.	Groundwater Management Permit terminated	17
Former Lemay Property - Lots 4 & 5	200805046	21 and 25 Saw Mill Road, Gilford	Volatile organic compounds detected in groundwater above groundwater standards.	Monitored natural attenuation until groundwater consistently met groundwater standards.	None	3.24
<b>Total Acreage</b>						<b>1,367</b>