

**Table 5**  
**SUMMARY OF SITES WHERE REMEDIAL ACTIONS WERE CONDUCTED**  
**BETWEEN**  
**OCTOBER 1, 2010 AND September 30, 2011**

SITE NAME	SITE NUMBER	SITE ADDRESS	COMMENTS	INSTITUTIONAL CONTROLS	ACREAGE
Wilcom, Inc.	199910017	73 Daniel Webster Highway, Belmont	Copper reported in groundwater above groundwater standard. Copper and lead detected in soil above soil standards. Remedial action plan established approved site specific standards.  Soils with lead and copper concentrations above the approved site specific soil remediation standards were removed and disposed of at a permitted facility.	NONE	7
DDR Seabrook (Former Venture Industries)	198705069	700 Lafayette Road, Seabrook	Polynuclear aromatic hydrocarbons detected in soil above soil standards - deemed background. Volatile organic compounds, pentachlorophenol, and antimony detected in groundwater above groundwater standards.	Groundwater Management Permit (Monitored Natural Attenuation)	46.47
Beebe Rubber Co.	199105038	20 Marshall Street, Nashua	Chlorinated volatile organic compounds detected in soil and groundwater above soil and groundwater standards.  Identified contaminated soil removed.	Notice of Activity and Use Restriction Groundwater Management Permit	4.75
Sunrise Sunoco (Former Mr. Mike's)	199212034	1162 Route 119, Rindge	Chlorinated volatile organic compounds detected in groundwater above groundwater standards.	None Groundwater monitored until contaminant concentrations consistently met groundwater standards.	1.43
<b>Total Acreage</b>					<b>59.65</b>